

YSOFT USB CARD READER 3 FIRMWARE 2.7.1 RELEASE NOTES

The 2.7.1 USB v3 firmware release contains the following fixes:

- Y Soft configuration cards were not working in 2.7.0 firmware release